






# PYTHAGORAS

[www.blum.com](http://www.blum.com)



**blum**  
PYTHAGORAS





-50°	A . . . . CLIP top BLUMOTION B . . . . CLIP top ohne Feder CLIP top unsprung CLIP top sans ressort CLIP top senza molla CLIP top sin muelle CLIP top bez pružiny x . . . . INSERTA = 9 x . . . . Schrauben = 5 screw-on à visser viti por atornillado Šroubování	<p>N° 26</p> <p>A 79B34:0 B 78A5450 C 173H7100 D 171A5500</p> <p>N° 27</p> <p>A 79B34:0 B 78A5450 C 173H7130</p> <p>N° 28</p> <p>A 79B34:0 B 78A5450 C 173H7100 D 171A5040</p> <p>N° 29</p> <p>A 79B34:1 B 78A5451 C 173H7100 D 171A5500</p> <p>N° 30</p> <p>A 79B34:1 B 78A5451 C 173H7130</p> <p>N° 31</p> <p>A 79B34:1 B 78A5451 C 173H7100 D 171A5040</p> <p>N° 32</p> <p>A 79B34:3 B 78A5453 C 173H7100 D 171A5500</p> <p>N° 33</p> <p>A 79B34:3 B 78A5453 C 173H7100</p> <p>N° 34</p> <p>A 79B34:3 B 78A5453 C 173H7100 D 171A5010</p> <p>N° 35</p> <p>A 71B95:0 B 70T9550.TL C 173H7100 D 171A5500</p>
-45°		
-40°		
-35°	A B A + B	
-30°		
-25°	<p>N° 11</p> <p>A 79B34:1 B 78A5451 C 175H7190 D 171A5070</p> <p>N° 12</p> <p>A 79B34:3 B 78A5453 C 175H9160 D 171A5500</p> <p>N° 13</p> <p>A 79B34:3 B 78A5453 C 175H7190.22</p> <p>N° 14</p> <p>A 79B34:3 B 78A5453 C 175H7190 D 171A5070</p> <p>N° 15</p> <p>A 71B95:0 B 70T9650.TL C 173H7100 D 171A5500</p>	
-20°		
-15°		
-10°		
-5°		

	<b>N° 16</b>  A 71B97.0 B 70T9750.TL C 173H7100 D 171A5010	<b>N° 46</b>  A 71B96.0 B 70T9650.TL C 173H7100 D 171A5070	<b>N° 1</b>  A 71B95.0 B 70T9550.TL C 173H7100 D 171A5010	<b>N° 36</b>  A 71B95.0 B 70T9550.TL C 173H7100 D 171A5010	<b>+5°</b>
	<b>N° 17</b>  A 79B94.4 B 78A9454 C 175H7190.22 D 171A5500	<b>N° 47</b>  A 79B94.4 B 78A9454 C 175H7190.22 D 171A5500	<b>N° 2</b>  A 79B94.4 B 78A9454 C 173H7100 D 171A5500	<b>N° 37</b>  A 79B94.4 B 78A9454 C 173H7100 D 171A5500	<b>+10°</b>
<b>N° 55</b>  A 79B95.5 B 78A9555 C 173H7100 D 171A5500	<b>N° 18</b>  A 79B95.5 B 78A9555 C 175H7190 D 171A5500	<b>N° 48</b>  A 79B95.5 B 78A9555 C 173H7130 D 171A5500	<b>N° 3</b>  A 79B94.4 B 78A9454 C 175H7190	<b>N° 38</b>  A 79B94.4 B 78A9454 C 175H9160	<b>+15°</b>
<b>N° 56</b>  A 79B95.5 B 78A9555 C 175H9160	<b>N° 19</b>  A 79B95.5 B 78A9555 C 175H7190.22	<b>N° 49</b>  A 79B95.5 B 78A9555 C 175H7190	<b>N° 4</b>  A 79B95.5 B 78A9555 C 173H7100 D 171A5070	<b>N° 39</b>  A 79B94.4 B 78A9454 C 173H7100 D 171A5070	<b>+20°</b>
<b>N° 57</b>  A 79B95.6 B 78A9556 C 173H7100 D 171A5500	<b>N° 20</b>  A 79B95.6 B 78A9556 C 175H7190 D 171A5500	<b>N° 50</b>  A 79B95.6 B 78A9556 C 173H7100 D 171A5500	<b>N° 5</b>  A 79B95.5 B 78A9555 C 173H7100 D 171A5010	<b>N° 40</b>  A 79B94.6 B 78A9456 C 173H7100 D 171A5500	<b>+25°</b>
<b>N° 58</b>  A 79B95.6 B 78A9556 C 173H7130	<b>N° 21</b>  A 79B95.6 B 78A9556 C 175H7190.22	<b>N° 51</b>  A 79B95.6 B 78A9556 C 175H7190	<b>N° 6</b>  A 79B95.6 B 78A9556 C 173H7100	<b>N° 41</b>  A 79B94.6 B 78A9456 C 175H9160	<b>+30°</b>
<b>N° 59</b>  A 79B95.6 B 78A9556 C 173H7100 D 171A5040	<b>N° 22</b>  A 79B95.6 B 78A9556 C 175H7190.22 D 171A5010	<b>N° 52</b>  A 79B95.6 B 78A9556 C 173H7100 D 171A5070	<b>N° 7</b>  A 79B95.6 B 78A9556 C 173H7100 D 171A5010	<b>N° 42</b>  A 79B94.6 B 78A9456 C 173H7100 D 171A5070	<b>+35°</b>
<b>N° 109</b>  A 79B94.8 B 78A9458 C 175H7190 D 171A5010	<b>N° 23</b>  A 79B96.8 B 78A9658 C 175H7190 D 171A5500	<b>N° 108</b>  A 79B94.8 B 78A9458 C 175H7190 D 171A5040	<b>N° 8</b>  A 79B94.8 B 78A9458 C 175H9160 D 171A5500	<b>N° 43</b>  A 79B94.8 B 78A9458 C 173H7100 D 171A5500	<b>+40°</b>
<b>N° 60</b>  A 79B96.8 B 78A9658 C 173H7100	<b>N° 24</b>  A 79B35.8 B 78T5550 C 175H7190.22	<b>N° 53</b>  A 79B96.8 B 78A9658 C 173H7100	<b>N° 9</b>  A 79B35.8 B 78T5550 C 173H7100	<b>N° 44</b>  A 79B94.8 B 78A9458 C 175H9160	<b>+45°</b>
<b>N° 61</b>  A 79B96.8 B 78A9658 C 173H7100 D 171A5010	<b>N° 25</b>  A 79B96.8 B 78A9658 C 175H7190 D 171A5070	<b>N° 54</b>  A 79B96.8 B 78A9658 C 173H7100 D 171A5010	<b>N° 10</b>  A 79B35.8 B 78T5550 C 173H7100 D 171A5010	<b>N° 45</b>  A 79B94.8 B 78A9458 C 173H7100 D 171A5070	<b>+50°</b>
 A B C D	 A B C D	 A B C D	 A B C D	 A B C D	

Julius Blum GmbH  
Furniture Fittings Mfg.  
6973 Höchst, Austria  
Tel.: +43 5578 705-0  
Fax: +43 5578 705-44  
E-mail: [info@blum.com](mailto:info@blum.com)  
[www.blum.com](http://www.blum.com)

